

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

HS1100
NE
> 1
1.443 mi.
7620 ft.

POPULAR FORD (VACANT) SHOWROOM
2505 CONEY ISLAND AVE
BROOKLYN, NY

NY Spills S113818854
N/A

Site 1 of 2 in cluster HS

Relative:
Higher

Actual:
13 ft.

SPILLS:

Name: POPULAR FORD (VACANT) SHOWROOM
Address: 2505 CONEY ISLAND AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1303775 / 2015-10-19
Facility ID: 1303775
Facility Type: ER
DER Facility ID: 171031
Site ID: 484273
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: D4
SWIS: 2401
Spill Date: 2013-03-13
Investigator: RMPIPER
Referred To: Not reported
Reported to Dept: 2013-07-09
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2013-07-09
Spill Record Last Update: 2015-10-19
Spiller Name: TOM BALDWIN
Spiller Company: POPULAR FORD (VACANT) SHOWROOM
Spiller Address: 2505 CONEY ISLAND AVE
Spiller Company: 999
Contact Name: TOM BALDWIN
DEC Memo: "Cross Ref old spill #9202189 (closed in 2000) 7/9/2013 - Sangesland spoke to Tom Baldwin (Ford Properties in Michigan) He said the dealership is closed 2 years and they are trying to clean the site up to sell it. During a Phase 1-2 they found a buried tank on the site from an old gas station from the pre 1960's time. He's planning on pulling this tank and will deal with whatever he finds at that time. Some soil borings were done (all clean), but ground water shows some hits. 10/19/15- DEC Piper - Based on the work to date, no further action is warranted. This spill is closed. See report in Dec docs if warranted. "

Remarks: "Property bought location in 60s and it that time the property was an old gas station. The dealership has since closed x 2 years ago. In attempts to sell property bore tests show no soil impact but there is ground water affected from 10 - 13 feet. Further is pending DEC recommendations."

All Materials:

Site ID: 484273
Operable Unit ID: 1233958
Operable Unit: 01

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Material ID: 2232902
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: Not reported
Units: Not reported
Recovered: Not reported
Oxygenate: Not reported